

# Oil Field Environmental Incident Summary

**Incident:** 20150630074832      **Date/Time of Notice:** 06/30/2015 07:48

**Responsible Party:** BOSQUE DISPOSAL SYSTEMS, LLC

**Well Operator:** BOSQUE DISPOSAL SYSTEMS, LLC

**Well Name:** JESSICA SWD 1

**Field Name:** BLUE BUTTES

**Well File #:** 90243

**Date Incident:** 6/29/2015      **Time Incident:** 17:30

**Facility ID Number:**

**County:** MCKENZIE

**Twp:** 150

**Rng:** 95

**Sec:** 23

**Qtr:**

**Location Description:**

**Submitted By:** Al; Hunt

**Received By:**

**Contact Person:** Al; Hunt  
420 THROCKMORTON ST STE 640  
FORT WORTH, TX 76102-3723

**General Land Use:** Well/Facility Site

**Affected Medium:** Well/Facility Soil

**Distance Nearest Occupied Building:**

**Distance Nearest Water Well:**

**Type of Incident:** Valve/Piping Connection Leak

**Release Contained in Dike:** Yes - Within Dike

**Reported to NRC:** No

	Spilled	Units	Recovered	Units	Followup	Units
Oil						
Brine	3	Barrels	3	Barrels		
Other						

**Description of Other Released Contaminant:**

**Inspected:**

**Written Report Received:**

**Clean Up Concluded:**

**Risk Evaluation:**

None

**Areal Extent:**

***Potential Environmental Impacts:***

None

***Action Taken or Planned:***

Isolated, de-pressured, repaired.

***Wastes Disposal Location:***

***Agencies Involved:***

***Updates***

---

***Date:*** 6/30/2015    ***Status:*** Reviewed - Assigned to Other Agency

***Author:*** O'Gorman, Brian

***Updated Oil Volume:***

***Updated Salt Water Volume:***

***Updated Other Volume:***

***Updated Other Contaminant***

***Notes:***

Release, due to a valve/piping connection leak, remained within diking, according to the report. NDIC retains oversight.